

Form C

Information Needed to Declare Exemption

National Emission Standards for Hazardous Air Pollutants for

Glass Manufacturing Area Sources

40 CFR part 63 subpart SSSSSS

(<http://www.epa.gov/ttn/atw/area/fr26de07.pdf>)

Received

JUL 24 2008

Office Of Air, Waste
And Toxics

1. Business Name: BULLSEYE GLASS COMPANY
2. Owner/Operator Name: ERIC E. DURRIN
3. Mailing Address: 3722 SE 21ST AVE., PORTLAND, OR 97202
4. E-mail Address: ERICDURRIN@BULLSEYEGLASS.COM
5. Address (physical location) of Source: 3722 SE 21ST AVE., PORTLAND, OR 97202
6. Primary SIC and NAICS codes: 3211 327211
7. Glass products manufactured: COLORED ART GLASS

8. Do you use a continuous furnace? ☐ Yes ☒ No

9. Amount of glass produced: 2,500 tons per year

10. Do you add any of the following compounds to your furnace charge*:

Arsenic ☒ Yes ☐ No

Cadmium ☒ Yes ☐ No

Chromium ☒ Yes ☐ No

Lead ☒ Yes ☐ No

Manganese ☒ Yes ☐ No

Nickel ☒ Yes ☐ No

*Note that these metals are typically found in glass formulation additives; contact your supplier if you're unsure.

11. Although I am not currently subject to the Glass Manufacture's NESHAP, I will keep records of furnace types, glass production, and metal HAP compounds used in furnace charges. ☒ Yes ☐ No

12. Certification

I certify that, based on information and belief formed after reasonable inquiry, the statements and information in this report and the supporting enclosures are true, accurate and complete.

Print the name of the "Responsible Official*" for the facility:

ERIC E. DURRIN
Name of Responsible Official

CONTROLLER
Title

503-232-8887
Phone Number

*A "Responsible Official" can be:

- The president, vice-president, secretary, or treasurer of the company who owns the facility
- The owner of the facility
- The plant engineer or supervisor
- A government official if the facility is owned by the Federal, State, City, or County government
- A ranking military officer if the facility is located on a military base

Eric E. Durrin
Signature of "Responsible Official"

07/22/08
Date

Keep a copy of this form for your records.

Mail the original to:

Region 10 Office of the EPA
Director, Office of Air, Waste and Toxics
1200 6th Ave., Suite 900, OAQ-107
Seattle, WA 98101

Mail or fax a copy to:

Department of Environmental Quality
Attn: Jerry Ebersole
811 SW Sixth Ave
Portland, OR 97204
Fax: 503-229-5675

